

Excellent Integrated System Limited

Stocking Distributor

Click to view price, real time Inventory, Delivery & Lifecycle Information:

Molex Connector Corporation 0640000074

For any questions, you can email us directly: <u>sales@integrated-circuit.com</u>



Distributor of Molex Connector Corporation: Excellent Integrated System Limited Datasheet of 0640000074 - REPAIR KIT FOR AT-HEAD Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com

one company > a world of innovation

This document was generated on 08/09/2012 PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION Part Number: <u>64000-0074</u> EU RoHS China RoHS Status: Active **Compliance Status Description:** Hand Tool Repair Kit Not Reviewed REACH SVHC **Documents:** Not Reviewed RoHS Certificate of Compliance (PDF) Low-Halogen Status Not Reviewed Need more information on product General environmental compliance? Product Family Application Tooling Series T0103 Email productcompliance@molex.com Comments 0194110180 (4 rings, c.e.)|0192790160 (2 jaw return For a multiple part number RoHS Certificate of springs)|0192790168 (2 pivot pins)|0194110177 (4 Compliance, click here rings, b.e.)|0192280397 (4 shims, .005")|0192790145 (2 cam follower rods, 4.75mm dia.) Please visit the Contact Us section for any Function Crimp non-product compliance questions. Geographic Area Global Level of Automation Manual More Detailed Tech Information applicationtooling@molex.com Product Name N/A Search Parts in this Series www.molex.com//review/apptool_survey.html Survey T0103Series Tool Type Repair Kit 756054502112 UPC

Material Info

This document was generated on 08/09/2012

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION