

Excellent Integrated System Limited

Stocking Distributor

Click to view price, real time Inventory, Delivery & Lifecycle Information:

Molex Connector Corporation 0638132450

For any questions, you can email us directly: sales@integrated-circuit.com



Distributor of Molex Connector Corporation: Excellent Integrated System Limited

Datasheet of 0638132450 - EXTRACT TOOL FOR CP 0.6 CRP TERM


Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com

Extractor Tool for 0.6mm (.02") CP Crimp Terminals

Extractor Tool HD-50423-1



Application Tooling Specification Sheet



Order No. 63813-2450

FEATURES

This Extractor Tool is for the removal of 64322 Series female terminals from CMC connector.

SCOPE


Products: 0.6mm (.02") CP Crimp Female Terminal for Power CMC Receptacle.

Terminal Series No.	Terminal Order No.		Housing Series No.
64322	64322-1019	64322-1229	64318, 64319,
	64322-1029	64322-1319	64326,
	64322-1219	64322-1329	64320 and 64321

OPERATION:

When removing a damaged crimped wire from the CMC connector follow the steps below:

- 1. The secondary lock on the CMC connector will need to be opened first. See Figure 1.
- 2. Using a screwdriver insert the flat edge under the tab of the secondary lock and pull up. Use your fingers to open the lock completely.



Doc No: ATS-638132450 Revision: A

Release Date: 07-01-10 Revision Date: 07-01-10 **UNCONTROLLED COPY**

Page 1 of 2




Distributor of Molex Connector Corporation: Excellent Integrated System Limited

Datasheet of 0638132450 - EXTRACT TOOL FOR CP 0.6 CRP TERM

Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com

Extractor Tool for 0.6mm (.02") CP Crimp Terminals

3. Position the blades of the extraction tool into the two small cavities of the slot in the front face of the housing as shown in Figure 2. Use the identifying markings on both the front and back of the connector to locate the opening used to extract the crimped wire.



- 4. Push extractor tool into the desired slot until it clicks or comes to a stop. Do not force the extractor tool any further or there can be damage to the housing.
- 5. Gently push the wire forward towards the housing and then pull out of the CMC housing.
- 6. Molex does not offer repair parts for Extractor Tools due to the inexpensive nature of these tools.

http://www.molex.com

Doc No: ATS-638132450 Release Date: 07-01-10 **UNCONTROLLED COPY** Page 2 of 2 Revision: A Revision Date: 07-01-10