

## Excellent Integrated System Limited

Stocking Distributor

Click to view price, real time Inventory, Delivery & Lifecycle Information:

[Molex Connector Corporation](#)  
[0622018782](#)

For any questions, you can email us directly:

[sales@integrated-circuit.com](mailto:sales@integrated-circuit.com)

This document was generated on 05/02/2016

**PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION**


**Part Number:** [0622018782](#)  
**Status:** **Active**  
**Description:** Daughter Card Module Installation Press-In Tool

**Documents:**  
[RoHS Certificate of Compliance \(PDF\)](#)

| General                        |   |
|--------------------------------|---|
| Product Family                 | Application Tooling   |
| Series                         | T9999   |
| Function                       | Insertion   |
| Geographic Area                | Global  |
| Level of Automation            | Semi-Automatic  |
| More Detailed Tech Information | <a href="mailto:applicationtooling@molex.com">applicationtooling@molex.com</a>  |
| Product Name                   | Impact™   |
| Survey                         | <a href="http://www.molex.com/review/apptool_survey.html">www.molex.com/review/apptool_survey.html</a>  |
| Tool Type                      | Handtool  |
| UPC                            | 884982282131  |
| Warranty Disclaimer            | CAUTION: Molex tooling crimp specifications are valid only when used with Molex terminals and tooling manufactured by Molex and sold by Molex or authorized distributors ("Molex Tooling"). When using tooling other than Molex Tooling with Molex specific connector systems listed in our ATS documents, the Molex tooling qualification does not apply and the responsibility for full qualification of the connector system is that of the customer. Molex accepts no liability for connector performance or tooling support where tooling other than Molex Tooling is used or where Molex Tooling is modified. |

**Material Info**

| Reference - Drawing Numbers   |               |
|-------------------------------|---------------|
| Application Tooling Documents | ATS-622018782 |



|   |                   |
|---|-------------------|
| <b>EU ELV</b><br>Not Reviewed   | <b>China RoHS</b> |
| <b>EU RoHS</b><br>Not Reviewed  |                   |
| <b>REACH SVHC</b><br>Not Reviewed   |                   |
| <b>Halogen-Free Status</b><br>Not Reviewed  |                   |
| <b>Need more information on product environmental compliance?</b>   |                   |
| Email <a href="mailto:productcompliance@molex.com">productcompliance@molex.com</a><br>Please visit the <a href="#">Contact Us</a> section for any non-product compliance questions. |                   |
| China ROHS  | Not Reviewed      |
| ELV   | Not Reviewed      |

|   |
|---|
| <b>Search Parts in this Series</b><br>T9999 Series  |
| <b>Use With</b><br>Impact™ Daughtercard Signal Module Assembly (5-Pair by 14 Column Assemblies) 76060 |

This document was generated on 05/02/2016

**PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION**