

## **Excellent Integrated System Limited**

Stocking Distributor

Click to view price, real time Inventory, Delivery & Lifecycle Information:

Molex Connector Corporation 1301080094

For any questions, you can email us directly: sales@integrated-circuit.com



## Distributor of Molex Connector Corporation: Excellent Integrated System Limited

Datasheet of 1301080094 - 80W TWN 120V.60HZ.BIAX2LMPENDUNT

Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com



This document was generated on 07/06/2016

## PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

 Part Number:
 1301080094

 Status:
 Active

Overview: Wide-Area Lighting Products

Description: Super-Safeway™ Twin Tube 80W Fluorescent Work Light, Cord Type 16/3 SJTW

7.62m (25.0') Cord Length

**Documents:** 

RoHS Certificate of Compliance (PDF) Product Literature (PDF)

**Agency Certification** 

CŠA LR85374 UL E174254

General

Product Family Portable Lighting
Series 130108
NEMA Configuration Non-NEMA Crowfoot

Outlet None

Overview <u>Wide-Area Lighting Products</u>

Product Literature Order No
987650-8054
Product Name
Super-Safeway™
Type
Wide Area Lamps
UPC
78678813030
Woodhead
Yes

**Physical** 

Cord Length - Primary 7.62m (25.0')

Cord Length - Secondary N/A

Depth 190.75mm (7.510")
Duty Industrial

 Guard Included
 Yes

 Guard Type
 Clear Butyrate

 Height
 82.55mm (3.250")

 Length
 636.00mm (25.039")

Material - GuardButyrateMounting StyleStrapsPackaging TypeCartonSocket ConstructionN/A

Electrical

 Bulb Type
 Fluorescent

 Cord Type - Primary
 16/3 SJOW

 Lamp Type
 PL-L 40/41

 Lamp Wattage - Maximum
 80W

 Lumens
 6300

 On/Off Switch
 No

Voltage (Fixture) - Maximum 120VAC 60 HZ

**Material Info** 

Old Part Number 1050-PL



**China RoHS** 

EU ELV Not Reviewed

EU RoHS Not Reviewed

REACH SVHC
Not Reviewed
Halogen-Free
Status
Not Reviewed

Need more information on product environmental compliance?

Email <u>productcompliance@molex.com</u>
Please visit the <u>Contact Us</u> section for any non-product compliance questions.

China ROHS Not Reviewed ELV Not Reviewed

Search Parts in this Series

130108 Series

This document was generated on 07/06/2016

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION