



Excellent Integrated System Limited

Stocking Distributor




Click to view price, real time Inventory, Delivery & Lifecycle Information:

[Essentra Components \(formerly Richco, Inc.\)](#)
[TFCC-30-01](#)

For any questions, you can email us directly:

sales@integrated-circuit.com

PART NO.	MAX. NO. OF CONDUCTORS	"A" REF	"B"	"C"	"D"	"E"	"F" REF.	MATERIAL	ADHESIVE
TFCC-30-01	30	32 [1.26]	45+1.5/-0.5 [1.77]		18.6+1.2/-0.3 [.73]	3±0.2 [.12]	4.6 [.18]	NYLON 6/6 UL94 V-2 (RMS-74)	ARYLIC (RMS-350)
TFCC-40-01	40	54 [2.13]	67±1 [2.64]	15.8±0.5 [.62]	15.8±1 [.62]			NYLON 6/6 UL94 V-2 (RMS-01)	ARYLIC (RMS-430)
TFCC-50-01	50	65.2 [2.57]	78.4+1.5/-0.5 [3.09]		18.8+1.2/-0.3 [.74]	3.1±0.2 [.12]	4.7 [.19]	NYLON 6/6 UL94 V-2 (RMS-74)	ARYLIC (RMS-350)



NOTES:
1. PART DESIGNED IN MM, INCH CONVERSION IS FOR REFERENCE ONLY.

REV.			DESCRIPTION			TITLE: TENSION FLAT CABLE CLAMP			DWG IN MM [IN]		PRINT TYPE
I	SEE CO 200715 FOR CHANGES	SK	10/03/11	CREATED USING SOLIDWORKS	FILE #: TFCC	DWN: SK	APP: BR	FINAL		CA	
H	SEE CO 200082 FOR CHANGES	SK	12/06/07	GENERAL TOLERANCE ±0.25 MM UNLESS OTHERWISE STATED	SHEET: 1 OF 1	DT: 08/25/05	CHKD: RT	PART #	SEE TABLE		
G	SEE CO 200041 FOR CHANGES	SK	09/28/07		RE: RICHCO, INC.	RICHCO, INC.					
F	REDRAWN, SEE ECN #1043 FOR CHANGES	SK	08/25/05		ENG@RICHCO-INC.COM		(773) 539-4060				
-	SEE ENGINEERING FOR REVISIONS A-E	---	---								
REV.		ENGR.	DATE								