

Excellent Integrated System Limited

Stocking Distributor

Click to view price, real time Inventory, Delivery & Lifecycle Information:

<u>3M</u> <u>M1BXA-1040K</u>

For any questions, you can email us directly: <u>sales@integrated-circuit.com</u>




Distributor of 3M: Excellent Integrated System Limited Datasheet of M1BXA-1040K - IDC CABLE - MSR10A/MC10F/X Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com

3M[™] IDC Ribbon Cable Socket

 $.100" \times .100"$ for .050" Pitch Cable

891 Series



- Preassembled, packaging on swords for easy loading of manual and semi-automatic assembly equipment
- "Bumps" are designed to prevent premature latch locking during shipment
- Optional double-sided adhesive pull tab for easy unplugging
- Double-recessed cover for cable terminating from either side virtually eliminating the need for single-recessed cover connectors
- Military polarization, with or without centerbump
- See the Regulatory Information Appendix (RIA) in the "RoHS compliance" section of www.3Mconnectors.com for compliance information (RIA E1 & C1 apply)

Date Modified: July 18, 2012

TS-0449-L Sheet 1 of 3

Insulation:					
Material:	Glass Filled Polyester (PBT)				
Flammability:	UL 94V-0				
Color:	Gray				
Contact:					
Material:	Phosphor Bronze				
Plating:					
Underplating:	50 μ" [1.27 μm] Nickel				
Wiping Area:	30 µ" [0.76 µm] Gold				
Wire Accommodation:	26 and 28 AWG Stranded				
Marking:	3M Logo and Orientation Triangle				
Current Rating:		1 line	6 Adjacent Lines	All Lines	
	28 AWG	4.25	1.75	1.25	
	26 AWG	4.50	2.25	1.50	
	Rating Conditions: EIA-364-070 Method 2, 30°C maximum temperature rise, 20% derated. Reference appropriate 3M Product Specification for detailed current derating curves.				

Insulation Resistance:	$>\!1\times10^{9}\Omega$ at 500 $V_{_{DC}}$
Withstanding Voltage:	1,000 $\mathrm{V}_{\mathrm{RMS}}$ at Sea Level

Temperature Rating: -55°C to +105°C

UL File No.: E68080




Distributor of 3M: Excellent Integrated System Limited Datasheet of M1BXA-1040K - IDC CABLE - MSR10A/MC10F/X Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com

3M[™] IDC Ribbon Cable Socket

 $.100"\times.100"$ for .050" Pitch Cable

891 Series



ЗМ

Electronic Solutions Division http://www.3Mconnectors.com 3M is a trademark of 3M Company. For technical, sales or ordering information call 800-225-5373




Distributor of 3M: Excellent Integrated System Limited Datasheet of M1BXA-1040K - IDC CABLE - MSR10A/MC10F/X Contact us: sales@integrated-circuit.com Website: www.integrated-circuit.com

3M[™] IDC Ribbon Cable Socket

 $.100^{\prime\prime} \times .100^{\prime\prime}$ for .050" Pitch Cable

891 Series



3M Electronic Solutions Division http://www.3Mconnectors.com 3M is a trademark of 3M Company. For technical, sales or ordering information call 800-225-5373



Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one (1) year from the time of purchase. 3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. Except where prohibited by law, 3M will not be liable for any indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.



3M Electronics Solutions Division 6801 River Place Blvd. Austin, TX 78726-9000 U.S.A. 1-800-225-5373 www.3Mconnectors.com

Please recycle. Printed in USA. © 3M 2012. All rights reserved. RIA-2217B-E

3M is a trademark of 3M Company.